

VEHICLE INSPECTION REPORT

HX17NTY

Daf CF 460

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 01/03/2017

Colour WHITE

Gearbox AUTOMATIC

Year 2017

VIN XLRTGM4300G128108

Axle Combi 6x2

Mileage 585,751 Km Warranted

Body Style Tractor Unit

Steering Combi Mid-Lift

Fuel Type Diesel

Cab Type SPACE CAB

WARNING LIGHTS ON DASH, INPUT ERROR ON MILEAGE HISTORY TWIN LINE PTO HYDRAULICS, GARDNER DENVER HYDRAPAK

Tyres



NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features

- Bluetooth connection
- Cruise control
- Digital radio
- Air conditioning
- Front electric windows
- Central locking
- Cloth seat trim


Photos







Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips

2: Bumper Front
Chipped
Multiple Chips



3: Door Mirror Assy nsf
Broken
Replace

4: Door Mirror Assy nsf
Scuffed (Unpainted)
UpTo 100mm



5: Screen Front
Chipped
Over 10mm

6: Dash Warning Lights
Displayed
No Action

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	OK	Odour	-
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	Fault		