Carr Hill Industrial Estate
Doncaster
DN4 8DE
01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

PN24JTZ

Renault Master 35 2.3

Inspection

Serious Damage?	No

Vehicle

VAT	Plus VAT
V5	Buyer To Apply
Cap Code	RTMA2343RRBDTM2 4 L

Details

Location	Doncaster	**Fuel Type**	DIESEL	**Body Style**	Traffic Management
Reg. date	20/06/2024	**GVW**	3500kg	**Gearbox**	MANUAL
Year	2024	**Colour**	WHITE	**Gears**	6
Mileage	49,479 Miles Not Warranted	**VIN**	VF6VG000472370280		

AD-BLUE, E/ MIRRORS

Tyres

NSF	
NSR	
OSF	
OSR	
Spare	


Features

- Bluetooth connection
- Auxiliary input socket
- Drivers airbag
- Cruise control
- Digital radio
- Central locking
- Navigation system
- Air conditioning
- Cloth seat trim
- Park assist camera
- Front electric windows


Photos














12:00
8°C
49479 miles
9257.9 miles






RENAULT TRUCKS
VF6VG000A7237028
3500 Kg
6000 Kg
1- 1850 Kg
2- 2100 Kg
DONG
99 Route de Lyon
69802 Saint-Priest Cedex France

















HIGHWAY MAINTENANCE
PN24 JTZ










Condition Check



Damage Photos



1: Bumper Front
Scratched
Over 100mm Thru Paint



2: Door Mirror Assy nsf
Scuffed (Unpainted)
Over 100mm



3: Door nsf
Scratched
Over 25mm Thru Paint



4: Sill ns
Dented
With Paint Damage



5: B Post ns
Chipped
Multiple Chips




6: B Post os
Scratched
Over 25mm Thru Paint



7: Door osf
Scratched
Over 25mm Thru Paint



8: Door Moulding osf
Scuffed (Unpainted)
Over 100mm



9: Dash Warning Lights
Displayed
No Action

Interior

Carpet Condition	OK	**Upholstery Condition**	OK
Seat Condition	OK	**Odour**	No

Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	Fault